



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Biskra

Defect ID : 81

### Defect Details

During Loading operation ( STS) from BITU ATLANTIC, minor leak found on vessels hose. At the time of Leak the Manifold pressure was zero on Biskra and 1 bar on Bitu Atlantic.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

### Applicable Dates

Date Raised : 15-Apr-2022

Date Completed : 26-Apr-2022

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	08/Sep/2022
Potential to become a serious accident : High			Recurrence : Low		

### Causes

Wear and Tear

### Corrective Action

Stopped Loading immediately and Disconnected the hose. Change the hose and Resumed Loading.

### Preventive Action

Hoses to be pressure tested regularly and During connection laying should be proper.

### Applicable Tags

### Root Causes- Job Factor

Excessive Wear and Tear

### Follow Up

On	By	Follow Up	
----	----	-----------	--

26/Apr/2022	Ayaz Eqbal Upadhye   Staff Code - 10346 - MST	The damaged hose is not in use anymore.	
-------------	--	---	--

**Before & After Pictures**

Before	After
--------	-------



