



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 72

### Defect Details

After cargo operation, fire extinguisher from locker not properly secured.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Knowledge / Skill	Office Dept :	Safety

### Applicable Dates

Date Raised : 15-Jan-2023

Date Completed : 01-Feb-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Feb/2023

Potential to become a serious accident : Low

Recurrence : Low

### Causes

Lack of skills/training

### Corrective Action

Proper securing all items before departure

### Preventive Action

Additional training regarding preparation for sea

### Applicable Tags

#### Root Causes- Job Factor

Inadequate Work Standards

#### Root Causes- Management Factors

Inadequate Monitoring / Supervision

#### Root Causes- Personal Factor

Lack of Discipline

**Direct Causes- Unsafe Acts**

Failure to Follow Rules and Regulations

**Follow Up**

On	By	Follow Up	
30/Jan/2023	Adrian Tudor   Staff Code - 10513 - MST	Deck crew explained that all items should be properly secured after completion cargo operation.	

**Before & After Pictures**

Before	After
--------	-------