

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Demerara Defect ID: 72

Defect Details

After cargo operation, fire extinguisher from locker not properly secured.

Requisition Code:

Categories					
Primary :	Near Miss	Vessel Dept :	Deck		
Secondary :	Lack of Knowledge / Skill	Office Dept:	Safety		

Applicable Dates

Date Raised: 15-Jan-2023 Date Completed: 01-Feb-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	01/Feb/2023

Potential to become a serious accident: Low Recurrence: Low

Causes

Lack of skills/training

Corrective Action

Proper securing all items before departure

Preventive Action

Additional training regarding preparation for sea

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Near Miss Details Printed On: 05-Jun-2023 1/2

Lack of Discipline

Direct Causes- Unsafe Acts

Failure to Follow Rules and Regulations

Follow Up					
On	Ву	Follow Up			
30/Jan/2023	Adrian Tudor Staff Code - 10513 - MST	Deck crew explained that all items should be properly secured after completion cargo operation.			

Before & After Pictures		
Before	After	