

Maritec Tanker Management Private Limited

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.						
Vessel : Bitu Express				Defect ID : 333		
Defect Details						
During Defendering at Dakar anchorage, while picking up the fender onboard as because of swell fender moderately hit on ship's rail. As crew were holding the ropes secured with fender at both end, on one end it was not tightly hold to prevent any moderate movement during picking up. One of the crew quickly managed to escape from hit. No personal injury observed.						
Requisition Code :						
Categories						
Primary :	Near Mi	Near Miss		Dept :	Deck	
Secondary :	Other	Other		Dept :	Operations	
Applicable Dates						
Date Raised : 18-Feb-2024				Date Completed : 19-Feb-2024		
Other Details						
Priority :	Normal	QMS Elements R		- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	
Potential to become a serious accident : Medium				Recurrence : Low		
Causes						
Sea Swell, Not paying more attention for securing & holding the ropes attached with during rolling.						
Corrective Action						
After Defendering complition, Crew were briefed about paying more attention on personel safety while picking up any load during rolling and swell. If possible to wait for the load to stabalize in movement. Always hold the ropes tightly secured with load to have minimum movement.						
Preventive Action						
Detailed briefing to crew before such operations.						
CONTRIBUTING FACTORS						
Follow Up						
On	Ву	Follow	w Up			
Before & After Pictures						