



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu River

Defect ID : 31

Defect Details

During routine checks, leakage was found in the hose coupling of the lifeboat air support system.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

Applicable Dates

Date Raised : 18-Jul-2023

Date Completed : 24-Jul-2023

Other Details

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	04/Aug/2023
Potential to become a serious accident : Medium			Recurrence : Low		

Causes

Improper tightness of coupling.

Corrective Action

Teflon tape was fitted on the coupling and tightened. Air system retested, no more leakage.

Preventive Action

Follow maintenance schedule and instructions as per PMS and with guidance of manufacturer's maintenance manual.

Applicable Tags**Root Causes- Job Factor**

Inadequate Leadership and / or Supervision

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------

