



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu River

Defect ID : 31

### Defect Details

During routine checks, leakage was found in the hose coupling of the lifeboat air support system.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

### Applicable Dates

Date Raised : 18-Jul-2023

Date Completed : 20-Jul-2023

### Other Details

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Low		

### Causes

Improper tightness of coupling.

### Corrective Action

Teflon tape was fitted on the coupling and tightened. Air system retested, no more leakage.

### Preventive Action

Follow maintenance schedule and instructions as per PMS and with guidance of manufacturer's maintenance manual.

### Applicable Tags

### Follow Up

On	By	Follow Up	
----	----	-----------	--

### Before & After Pictures

Before	After
--------	-------

