



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 90

Defect Details

During maintenance on diesel oil emergency line filter ,after completion of the job cover wasn't tightened enough, and when filter was in service ,leakages occurred .
Immediately pumps was stopped and filter cover retightened .
All engine staff have been briefed and advised concerning this matter.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Other	Office Dept :	Technical

Applicable Dates

Date Raised : 18-Oct-2023

Date Completed : 01-Nov-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Nov/2023
Potential to become a serious accident : High			Recurrence : Medium		

Causes

Lack of work supervision, Pump cover was not tightened up properly.

Corrective Action

Firstly pump was stopped immediately, Then checked the integrity of pump covers & same was tightened up properly to avoid having any further leaks.

Preventive Action

Pump must be boxed up in presence of Senior engineer. Integrity of tightness for all nuts/bolts in the system must be checked and verified properly prior trying out any machinery.

CONTRIBUTING FACTORS

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Follow Up			
On	By	Follow Up	
01/Nov/2023	Nawin Khaware	Such activities must be recorded under unsafe condition/or unsafe act.	

Before & After Pictures	
Before	After