

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Near Miss Details

| 0 | | | | |
|-----|----|----|------|--|
| Gui | ın | ar | ICE. | |
| | | | | |

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Demerara Defect ID: 145

Defect Details

while re-filling SCABA bottles after fire drill, Air leakage found from connection of Air compressor, immediately stopped compressor and checked all connection, one of the o-ring was damaged, same time replaced with new o-ring.

Requisition Code:

| Categories | | | | | | |
|-------------|--|---------------|--------|--|--|--|
| Primary : | Near Miss | Vessel Dept : | Deck | | | |
| Secondary : | Inadequate or Poor Quality Purchasing | Office Dept: | Safety | | | |

Applicable Dates

Date Raised: 19-May-2024 Date Completed: 21-May-2024

Other Details

| Priority : | Normal | QMS Elements Ref : | - SELECT - | Verified By : | Nawin Khaware |
|-----------------------------------|--------|--------------------|------------|---------------|---------------|
| Show in Monthly Safety Meeting? : | No | SFI: | | Verified On: | 21/May/2024 |

Potential to become a serious accident: Low Recurrence: Low

Causes

General wear & tier,

Corrective Action

Leaks arrested by changing o-ring of connector.

Preventive Action

All LSA/FFA items to be maintained in good working condition all the time.

CONTRIBUTING FACTORS

Root Causes- Job Factor

Inadequate Maintenance

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Conditions

Near Miss Details Printed On: 12-Jun-2024 1/2

Defective Equipment, Machinery or Tools

Direct Causes- Unsafe Acts

Making Safety Devices Inoperative

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up

On By Follow Up

Before & After Pictures

After

Near Miss Details Printed On: 12-Jun-2024 2/2