

Maritec Tanker Management Private Limited

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel: Bahama Blue				Defect ID : 189					
Defect Details									
Vessel Arrival at St. Croix and proceeding to Pilot Station.Deck crew prepare the pilot ladder in port side while preparing pilot ladder they found out that the pilot ladder is in bad condition which is some strand are partly parted.									
Requisition Code :									
Categories									
Primary :	Near Mi	Near Miss		Dept :	Deck				
Secondary :	Mainten	Inadequate Maintenance / Wear and Tear		Dept :	Technical				
Applicable Dates									
Date Raised : 19-N	lov-2023			Date Completed : 25-Nov-2023					
Other Details									
Priority :	Normal	ormal QMS Elements		- SELECT -	Verified By :				
Show in Monthly Safety Meeting? :	No	, SFI :			Verified On :				
Potential to become a serious accident : Medium Recurrence : Medium									
Causes									
Corrective Action									
Preventive Action									
CONTRIBUTING FACTORS									
Root Causes- Job Factor									
Excessive Wear and Tear									
Root Causes- Management Factors									
Stores / Spares Issue									
Root Causes- Personal Factor									
Others									

Direct Causes- Unsafe Acts

Improper Lifting, Handling or Storage

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up							
On	Ву	Follow Up					
22/Nov/2023	Vitaliy Klimenko Staff Code - 10633 - MST	causes: Due to prolong exposure to sun and sea water pilot ladder rope and condition become bad. Corrective action: Life ring with line stand-by at the pilot boarding area, requesition raise for pilot ladder. Preventive Action: After use of pilot ladder secure in the shelter area and cover with canvas to prevent direct or prolong exposure in the sunight and sea water.					

Before & After Pictures

