

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.							
Vessel : Bitu Atlantic				Defect ID : 274			
Defect Details							
1 Scupper observed open on main deck while vessel at Anchor awaiting berthing instructions.							
Requisition Code :							
Categories							
Primary :	Near Mi	SS	Vessel Dept :		Deck		
Secondary :		Procedures not Followed		ept:	Safety		
Applicable Dates							
Date Raised : 21-Jun-2023				Date Completed : 21-Jun-2023			
Other Details							
Priority :	Normal	al QMS Elements Ref :		- SELECT -	Verified By :		
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :		
Potential to become a serious accident : Medium Recurrence : Medium							
Causes							
Corrective Action							
Preventive Action							
Applicable Tags							
Substandard Acts							
Failure to follow procedure							
Substandard Conditions							
Hazardous Environmental Condition							
Follow Up							
On	Ву	Follo	w Up				

Before & After Pictures				
Before	After			