



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 308

Defect Details

Crew member sitting in snap-zone area at unmooring operation.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Situational Awareness	Office Dept :	Crew

Applicable Dates

Date Raised : 22-Aug-2023

Date Completed : 22-Aug-2023

Other Details

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	06/Oct/2023
Potential to become a serious accident : High			Recurrence : High		

Causes

Lack of knowledge

Corrective Action

Crew member was asked to immediately go away from the area before heaving up the ropes further.

Preventive Action

All crew members were informed of the importance of staying clear of ropes during mooring/unmooring operation. Explain all crew involved the correct procedure of handling guide ropes.

CONTRIBUTING FACTORS

Root Causes- Personal Factor

Lack of Knowledge

Follow Up

On	By	Follow Up
----	----	-----------

22/Aug/2023	Cosmin Otelea Staff Code - 10502 - C/OFF	Crew member sitting in snap-zone area at unmooring operation.	
-------------	--	---	--

Before & After Pictures

Before	After
---------------	--------------