



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Express

Defect ID : 125

Defect Details

Oil spill on deck portside front of accommodation due to bunker line pipe leakage.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Safety

Applicable Dates

Date Raised : 22-Sep-2021

Date Completed :

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Medium		

Causes

Lack of maintenance and poor condition of bunker pipe material

Corrective Action

All crew were alerted, immediately oil spill reponse, commenced cleaning the affected area.

Preventive Action

Bunker line to be tested before each use.
That part of deck bunker pipe should be renewed. Company was informed.

Applicable Tags**Descriptions**

Pollution

Root Causes- Job Factor

Inadequate Maintenance

Substandard Conditions

Other Unsafe Conditions

Follow Up

On	By	Follow Up	
22/Sep/2021	Gelu Antin Staff Code - 10124 - MST	Bunker pipe was temporary repaired by ship staff. Bunker line was tested after temporary repairs by ship staff.	Link1 Link2

Before & After Pictures

Before **After**



