

# **Maritec Tanker Management**

### **Near Miss Details**

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 141

#### **Defect Details**

AN A.B. TRIED TO REPLACE A CHIPPING GUN WITHOUT ISOLATING THE AIR SUPPLY

Requisition Code:

Categories			
Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Office Dept:	Safety

#### **Applicable Dates**

Date Raised: 24-Apr-2023 Date Completed: 26-Apr-2023

Other Details	Otl	her	Dei	tai	ls
---------------	-----	-----	-----	-----	----

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	26/Apr/2023

Potential to become a serious accident: Low Recurrence: Low

#### Causes

LACK OF SAFE PRACTICE

#### **Corrective Action**

CORRECTED ON THE SPOT BY OOW AND BRIEFED AS PER SMS AND CSWP.

#### **Preventive Action**

EMPHASIS ON SAFE WORK PRACTICE TO BE RE-ORIENTATED AT EACH JOB TO BE CARRIED OUT

**Applicable Tags** 

#### **Root Causes- Personal Factor**

Lack of Knowledge

#### **Substandard Acts**

Failure to observe basic safety rules

#### Follow Up

Near Miss Details Printed On: 12-Sep-2023 1/2

On	Ву	Follow Up	
26/Apr/2023	Nawin Khaware	Agree with preventive measures, Remain observant & ensure regular compliance with same.	

## **Before & After Pictures**

Before After

Near Miss Details Printed On: 12-Sep-2023 2/2