

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Near Miss Details

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 310

Defect Details

During shifting foam glass pallets to MT Biskra OOW observed that one AB was sitting under the moving pallet. In this time due to improper lashing and crane wire balance one packet felled down close to AB position. Work stopped. Crew member instructed to stay always in safe zone. Crew involved instructed to use STOP Work procedure and to follow Safety Procedure.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Lack of Situational Awareness	Office Dept:	General			

Applicable Dates

Date Raised: 27-Aug-2023 Date Completed: 27-Aug-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	06/Oct/2023

Potential to become a serious accident: Low Recurrence: Low

Causes

Improper postion of the crew member. Lack of situational awarness.

Corrective Action

STOP Work procedure and crew member was warned to clear working area.

Preventive Action

Proper training provided to crew member.

CONTRIBUTING FACTORS

Root Causes- Personal Factor

Situational Awareness

Substandard Conditions

Inadequate Cargo Lashings or Stowage

Near Miss Details Printed On: 14-Dec-2023 1/2

Follow Up							
On	Ву	Follow Up					
Before & After Pictures							
Before			After				

Near Miss Details Printed On: 14-Dec-2023 2/2