

# Maritec Tanker Management

Ship File No: N/A
Office File No: N/A
Form No: N/A
Issue: N/A
Revision: N/A
Rev Date: N/A

## **Near Miss Details**

$\overline{}$				
Gu	ır	ıaı	nr	νΔ.
u	ľ	ı	ıı	<i>、</i> 、

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 144

### **Defect Details**

Crew member was opening the port of a running HFO purifier immediately after the starting of desludge countdown to check the leak from the bowl, the purifier has to be stable for atleast 2-3 mins, then it is advisable to open the inspection port of the purifier for oil leaks.

Requisition Code:

Categories			
Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Lack of Training	Office Dept:	Technical

## **Applicable Dates**

Date Raised: 28-Apr-2023 Date Completed: 05-May-2023

## Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	05/May/2023

Potential to become a serious accident: Low Recurrence: Low

#### Causes

Lack of knowledge.

#### **Corrective Action**

The crew member was instructed to go through the maual and advised the check the desludge time alawys before opening the inspection port.

## **Preventive Action**

The meeting was carried out in engine room and all the crew members were instructed about the operation and desludging of purifier.

#### **Applicable Tags**

## **Root Causes- Personal Factor**

Improper Assessment

Lack of Knowledge

#### **Direct Causes- Unsafe Acts**

Near Miss Details Printed On: 05-Jun-2023 1/2

Failure to Follow Repair / Maintenance Instructions

# **Job Factors**

Inadequate Supervision

# **Personal Factors**

Lack of Knowledge

# **Substandard Acts**

Failure to follow procedure

# Follow Up

On	Ву	Follow Up	
05/May/2023	Nawin Khaware	Concur with the preventive action plan. We could consider this NM as closed out now.	

# **Before & After Pictures**

Before After

Near Miss Details Printed On: 05-Jun-2023 2/2