

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 139

Defect Details

DURING MOORING OPERATION IT WAS OBSERVE THAT STBD MOORING WINCH ON ELECTRONIC ACTUATOR NOT ABLE TO RETURN TO ZERO POSITION BY IT SELF.

Requisition Code:

Categories				
Primary:	Near Miss	Vessel Dept :	Deck	
Secondary :	Other	Office Dept:	Safety	

Applicable Dates

Date Raised: 30-Mar-2023 Date Completed:

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	

Potential to become a serious accident: Medium Recurrence: Low

Causes

ELECTRONIC ACTUATOR FAILURE

Corrective Action

KEPT SWITCH THE ELECTRONIC POWER OFF DURING MOORING OPERATION AS ADDITION SELF CONTROL.

Preventive Action

CARYY OUT REPAIR OF EQUIPMENT AND FIX THE ISSUE.

Applicable Tags

Root Causes- Job Factor

Inadequate Tools and Equipment

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Follow Up

Near Miss Details Printed On: 08-Sep-2023 1/2

On	Ву	Follow Up	
19/Jun/2023	Nawin Khaware	Pls update here the latest status, provide either photographs/records etc if repair has been completed.	
26/May/2023	Nawin Khaware	I can't see any updates from vessel side, kindly advise if the issues has been resolved.	
21/Apr/2023	Nawin Khaware	Pls advise the present status of equipment.	
13/Apr/2023	Nawin Khaware	What is the present status of equipments.	

Before & After Pictures

Before	After
--------	-------

Near Miss Details Printed On: 08-Sep-2023 2/2