



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu River

Defect ID : 24

Defect Details

The laundry room drying machine filter is not cleaned after operation which can be a fire hazard.

Requisition Code :

Categories

| | | | |
|-------------|-------------------------|---------------|--------|
| Primary : | Near Miss | Vessel Dept : | Deck |
| Secondary : | Procedures not Followed | Office Dept : | Safety |

Applicable Dates

Date Raised : 30-Mar-2023

Date Completed : 31-Mar-2023

Other Details

| | | | | | |
|--|--------|--------------------|---------------------|---------------|---------------|
| Priority : | Normal | QMS Elements Ref : | - SELECT - | Verified By : | Nawin Khaware |
| Show in Monthly Safety Meeting? : | No | SFI : | | Verified On : | 13/Apr/2023 |
| Potential to become a serious accident : Low | | | Recurrence : Medium | | |

Causes

Lack of motivation to follow the proper procedures

Corrective Action

Crew debriefed about the fire hazard

Preventive Action

Poster posted at all dryers to avoid forgetfulness and recurrence

Applicable Tags**Root Causes- Personal Factor**

Lack of Discipline

Follow Up

| On | By | Follow Up | |
|----|----|-----------|--|
|----|----|-----------|--|

Before & After Pictures

Before



After

