

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Near Miss Details

\sim			
(411	ın	an	ce:
Ou	ıu	ai i	oc.

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Morbihan Defect ID: 157

Defect Details

on 30 May 2024 08:45 am safety officer carried safety inspection on deck and found out midship water tight door securing hook is damage and unable to secure the water tight door with the hook.

Requisition Code:

Categories					
Primary :	Near Miss	Vessel Dept :	Deck		
Secondary :	Poor Housekeeping	Office Dept:	Safety		

Applicable Dates

Date Raised: 30-May-2024 Date Completed: 11-Jun-2024

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	
		I			

Potential to become a serious accident : Medium Recurrence : Medium

Causes

Lack of maintenance

Corrective Action

requisition raise for metal securing hook and repair.

Preventive Action

proper maintenance and good house keeping needs to be maintained all the time. ensure securing arrangements of all W/T doors are maintained in good condition.

CONTRIBUTING FACTORS

Descriptions

Others

Root Causes- Job Factor

Inadequate Maintenance

Root Causes- Management Factors

Near Miss Details Printed On: 12-Jun-2024 1/3

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Others

Direct Causes- Unsafe Conditions

Poor Housekeeping

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Personal Factors

Not Applicable

Substandard Acts

Other Unsafe Acts

Follow Up

On	Ву	Follow Up	
10/Jun/2024	Nawin Khaware	ETC has been changed from "06 Jun 2024" to "30 Jun 2024".	
07/Jun/2024	Nawin Khaware	These securing hooks could also be fabricated onboard and same must be put back in place in the interim period and replace them once proper hooking arrangements are received onboard.	
30/May/2024	Christopher Rondael PILLER >br/> Staff Code - 10401 - C/OFF	requisition raise for metal securing hook and repair.	

Before & After Pictures

Before After

Near Miss Details Printed On: 12-Jun-2024 2/3









Near Miss Details Printed On: 12-Jun-2024 3/3