



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Morbihan

Defect ID : 157

Defect Details

on 30 May 2024 08:45 am safety officer carried safety inspection on deck and found out midship water tight door securing hook is damage and unable to secure the water tight door with the hook.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Poor Housekeeping	Office Dept :	Safety

Applicable Dates

Date Raised : 30-May-2024

Date Completed :

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Medium		

Causes

Lack of maintenance

Corrective Action

requisition raise for metal securing hook and repair.

Preventive Action

proper maintenance and good house keeping needs to be maintained all the time. ensure securing arrangements of all W/T doors are maintained in good condition.

CONTRIBUTING FACTORS

Descriptions

Others

Root Causes- Job Factor

Inadequate Maintenance

Root Causes- Management Factors

Inadequate Monitoring / Supervision
Root Causes- Personal Factor
Others
Direct Causes- Unsafe Conditions
Poor Housekeeping
Direct Causes- Unsafe Acts
Failure to Follow Repair / Maintenance Instructions
Job Factors
Inadequate Maintenance or Not Done as per Manufacturer's Schedules
Personal Factors
Not Applicable
Substandard Acts
Other Unsafe Acts

Follow Up


On	By	Follow Up	
10/Jun/2024	Nawin Khaware	ETC has been changed from "06 Jun 2024" to "30 Jun 2024".	
07/Jun/2024	Nawin Khaware	These securing hooks could also be fabricated onboard and same must be put back in place in the interim period and replace them once proper hooking arrangements are received onboard.	
30/May/2024	Christopher Rondael PILLER Staff Code - 10401 - C/OFF	requisition raise for metal securing hook and repair.	

Before & After Pictures

Before	After
---------------	--------------




Notification

 File Not Uploaded



Notification

 File Not Uploaded