



# Maritec Tanker Management Private Limited

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 91

### Defect Details

Thruster room portside fan was founded noisy , and imediately stopped .  
After dismantling was discovered that ball bearings are stucked , and should be replaced .  
A new PR will be raised for bearings replacement .

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Electrical
Secondary :	Other	Office Dept :	Technical

### Applicable Dates

Date Raised : 30-Oct-2023

Date Completed : 08-Nov-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Medium		

### Causes

Poor quality of ball bearings

### Corrective Action

Bearings shoul be replaced

### Preventive Action

Spares to be on board

### CONTRIBUTING FACTORS

#### Descriptions

Machinery / Equipment Damage

#### Root Causes- Job Factor

Excessive Wear and Tear

#### Substandard Conditions

**Defective Materials****Follow Up**

<b>On</b>	<b>By</b>	<b>Follow Up</b>	
08/Nov/2023	Nawin Khaware	Provide the present status of this item, where required spare parts are connected onboard.	
01/Nov/2023	Nawin Khaware	Provide the details of requisition number for requested spare parts/items.	

**Before & After Pictures**

<b>Before</b>	<b>After</b>
---------------	--------------