

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel:	Asphalt Teranga	Defect ID: 130	NCR # :	Is NCR ? : No

Defect Details

01.02.06 The deck needs a lot of maintenance. Because of neglect, the rust has sent in on the deck because of which the paint is peeling off from the deck and is giving a very bad visual appearance. The deck needs to be chipped, primered and painted . Lots of effort needed to bring the deck back in good condition.

Requisition Code:

Categories					
Primary :	Others	Inspector - Internal :	Jainish Bhatnagar	Vessel Dept:	Deck
Secondary :	Vessel Appearance	Inspector External :		Office Dept:	Technical
		Inspection Date :	01-Dec-2022		

Appl	امما	ماد	Dat	00
W^4401011	1.042	D 1 L G-IIII	111111111111111111111111111111111111111	

Date Raised: 01-Dec-2022 ETC: 01-May-2023 Date Completed:

Other Details				
Priority : Normal	Assigned By: Tech Suptd	Verified By :		
Display in Daily Meeting? : No	SFI:	Verified On:		

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	Ву	Follow Up	
12/Dec/2022	Jainish Bhatnagar		

Before & After Pictures

Before	After
--------	-------

Defect List Details Printed On: 17-Jul-2023 1/1