



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 131	NCR # :	Is NCR ? : No
--------------------------	-----------------	---------	---------------

Defect Details

01.02.05: The accommodation superstructure is showing a lot of rust weeping marks. The port holes of the accommodation have been painted without de-rusting them. As a result of which the rust has started to seep out from below the paint giving the port holes a very shabby look.

Requisition Code :

Categories

Primary :	Others	Inspector - Internal :	Jainish Bhatnagar	Vessel Dept :	Deck
Secondary :	Vessel Appearance	Inspector External :		Office Dept :	Technical
		Inspection Date :	01-Dec-2022		

Applicable Dates

Date Raised : 01-Dec-2022	ETC : 30-Apr-2023	Date Completed :
---------------------------	-------------------	------------------

Other Details

Priority : Normal	Assigned By : Tech Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
12/Dec/2022	Jainish Bhatnagar		

Before & After Pictures

Before	After
--------	-------