

Before

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

| Vessel: Saint James LG | | Defect ID: 323 | | | NCR#: | | Is NCR ?: No | |
|---|----------------------|----------------|-------------------------|-----|------------------|--------------|--------------|------------|
| Defect Details | | | | | | | | |
| Observed that purifier room electrical panel axial cooling fan has lots of carbon deposits. Same has to be cleaned. | | | | | | | | |
| Requisition Code: | | | | | | | | |
| Categories | | | | | | | | |
| Primary : | E/R Machinery | Inspec | tor - Internal: | | | Vessel Dept: | | Electrical |
| Secondary : | Electrical equipment | Inspec | tor External : | | | Office Dept: | | Technical |
| | | Inspec | tion Date : | 01- | -Jun-2023 | | | |
| Applicable Dates | | | | | | | | |
| Date Raised: 01-Jun-2023 | | | ETC: 15-Jul-2023 | | Date Completed : | | | |
| Other Details | | | | | | | | |
| Priority : Normal | | | Assigned By: Tech Suptd | | Verified By : | | | |
| Display in Daily Meeting? : No | | | SFI: | | | Verified On: | | |
| Causes | | | | | | | | |
| Corrective Action | | | | | | | | |
| Preventive Action | | | | | | | | |
| Applicable Tags | | | | | | | | |
| Follow Up | | | | | | | | |
| On | Ву | | Follow Up | | | | | |
| 27/Jun/2023 | Abhishe | k Gupta | | | | | | |
| Before & After Pictures | | | | | | | | |
| | | | | | | | | |

Defect List Details Printed On: 17-Jul-2023 1/1

After