



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 107	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Emergency light for starboard Liferaft was not providing proper illumination. Upon further investigation it was observed that plastic sheet was wrapped on the cover which was obstructing the spread out of the entire flux.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Wasi Ahmad	Vessel Dept :	Electrical
Secondary :	Life Saving Appliances	Inspector External :		Office Dept :	Safety
		Inspection Date :	01-Oct-2020		

Applicable Dates

Date Raised : 01-Oct-2020	ETC : 08-Oct-2020	Date Completed : 01-Oct-2020
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Ops Suptd	Verified By : Francis Timothy Monteiro
Display in Daily Meeting? : No	SFI :	Verified On : 03/Jun/2021

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
02/Nov/2020	Wasi Ahmad		

Before & After Pictures

Before	After
--------	-------

