

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Atlantic Defect ID: 106 NCR #: 9/2020 Is NCR ?: Yes

Defect Details

During pressure testing of Fire Line it was observed that one of the fire hydrant in the aft part (at the break of accommodation) was leaking.

Requisition Code:

Categories						
Primary :	LSA/FFA	Inspector - Internal:	Wasi Ahmad	Vessel Dept:	Deck	
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept:	Safety	
		Inspection Date :	01-Oct-2020			

Applicable Dates

Other	Details

Priority : Normal	Assigned By: Ops Suptd	Verified By : Francis Timothy Monteiro
Display in Daily Meeting? : No	SFI:	Verified On : 03/Jun/2021

Causes

PMS not followed

Corrective Action

Fire hydrant seat lapping done.

Preventive Action

Follow PMS schedule.

Applicable Tags

Follow Up

On	Ву	Follow Up	
02/Nov/2020	Wasi Ahmad		

Before & After Pictures

Before	After

Defect List Details Printed On: 08-Jun-2021 1/2

26 04 2021

File not found!