



## Maritec Tanker Management

### Defect List Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 102	NCR # :	Is NCR ? : No
--------------------------	-----------------	---------	---------------

#### Defect Details

Ballast Pump Over Board Valve Actuator Found leaking.

Requisition Code :

#### Categories

Primary :	Ballast	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :			

#### Applicable Dates

Date Raised : 02-Aug-2022	ETC : 03-Aug-2022	Date Completed : 02-Aug-2022
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Follow Up

On	By	Follow Up	
02/Aug/2022	Munna Kumar   Staff Code - 10065 - 2/E	Actuator open and overhauled with new o rings/seals fitted back tried out working satisfactory,	

#### Before & After Pictures

Before	After
--------	-------

