



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 178	NCR # :	Is NCR ? : No
--------------------------	-----------------	---------	---------------

Defect Details

PI, Manual Positions not plotted during port approaches and berthing
Requisition Code :

Categories

Primary :	Nav/Comm	Inspector - Internal :	Fiacre Fonseca	Vessel Dept :	Deck
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Operations
		Inspection Date :	11-Aug-2023		

Applicable Dates

Date Raised : 11-Aug-2023	ETC : 25-Aug-2023	Date Completed :
---------------------------	-------------------	------------------

Other Details

Priority : Urgent	Assigned By : Ops Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

PERSONAL FACTOR

Corrective Action

PLOTTED

Preventive Action

CONTROL

Applicable Tags

Job Factors

Other Job Factors

Follow Up

On	By	Follow Up	
18/Aug/2023	Fiacre Fonseca		

Before & After Pictures

Before	After
--------	-------

