

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Atlantic	Defect ID: 217	NCR # :	Is NCR ?: No

Defect Details

Brake support bolt below brake band, aft spring winch spacing excessive (12-15mm)

Requisition Code:

Categories					
Primary :	Dk Machinery	Inspector - Internal:	Fiacre Fonseca	Vessel Dept:	Deck
Secondary :	Mooring Winch	Inspector External :		Office Dept:	Operations
		Inspection Date :	16-Jul-2022		

Applicable Dates

Date Raised: 16-Jul-2022 ETC: 19-Sep-2022 Date Completed: 22-Jul-2022

Other Details

Priority: Normal Assigned By: Ops Suptd Verified By: Fiacre Fonseca

Display in Daily Meeting? : No SFI: Verified On : 18/Aug/2022

Causes

PMS not followed

Corrective Action

Support bolt adjusted to 3-4 mm

Preventive Action

Regular through inspection and maintenance as per the PMS.

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Root Causes- Management Factors

Inadequate Training

Root Causes- Personal Factor

Improper Assessment

Follow Up

Defect List Details Printed On: 17-Jul-2023 1/2

On	Ву	Follow Up	
28/Jul/2022	Fiacre Fonseca		

Before & After Pictures

Before







Defect List Details Printed On: 17-Jul-2023 2/2