



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 269	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

BWTS malfunction due to H2 gas sensor failure.

Requisition Code : BATL-SOT-V220220

Categories

Primary :	Ballast	Inspector - Internal :		Vessel Dept :	Electrical
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :			

Applicable Dates

Date Raised : 17-Feb-2023	ETC : 20-Mar-2023	Date Completed : 07-Apr-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Failure of H2 gas sensor.

Corrective Action

Inform office
Earlier requisition raised
Ballast exchange carried out as per approved ballast water management plan

Preventive Action

Keep H2 gas sensor as spare

Applicable Tags

Follow Up

On	By	Follow Up	
22/May/2023	Vitaly Maslov Staff Code - 10565 - C/E	Sensor renewed.	
07/Mar/2023	Stelian BOGHEA Staff Code - 10166 - C/E	Requisition raised BATL-SOT-V220220 on 07Nov2022.	

Before & After Pictures

Before



After

