

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue Defect ID : 178 NCR # : Is NCR ? : No

Defect Details

Pumproom Vent upper section completely oxidised, require attention.

Requisition Code:

Categories							
Primary :	Cargo Handling	Inspector - Internal :	Fiacre Fonseca	Vessel Dept:	Deck		
Secondary :	Cargo/ Ballast Machinery	Inspector External :		Office Dept:	Technical		
		Inspection Date :	20-Jan-2023				

Applicable Dates

Date Raised: 20-Jan-2023 ETC: 20-Apr-2023 Date Completed: 10-Feb-2023

Other Details

Priority: Normal Assigned By: Ops Suptd Verified By: Fiacre Fonseca

Display in Daily Meeting? : No SFI: Verified On : 09/May/2023

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Personal Factors

Defect List Details Printed On: 21-Jun-2023 1/2

Improper Motivation

Substandard Acts

Other Unsafe Acts

Substandard Conditions

Poor Housekeeping/ Cluttered Work Area

Follow Up

On	Ву	Follow Up	
27/Jan/2023	Fiacre Fonseca		

Before & After Pictures

Before

After



