



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 99	NCR # :	Is NCR ? : No
-----------------	----------------	---------	---------------

Defect Details

No Safety guard / Rope near Rescue boat / Life raft, very unsafe

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Fiacre Fonseca	Vessel Dept :	Deck
Secondary :	Life Saving Appliances	Inspector External :		Office Dept :	Operations
		Inspection Date :	25-Aug-2022		

Applicable Dates

Date Raised : 25-Aug-2022	ETC : 25-Sep-2022	Date Completed : 10-Sep-2022
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By : Fiacre Fonseca
Display in Daily Meeting? : No	SFI :	Verified On : 28/Sep/2022

Causes

Corrective Action

Preventive Action

Applicable Tags

Descriptions

Others

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Personal Factor

Others

Direct Causes- Unsafe Conditions

Inadequate Guards or Barriers

Follow Up

On	By	Follow Up	
29/Aug/2022	Muddassar Jafri		

Before & After Pictures

Before	After
--------	-------

