

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Kensington LG		Defect ID : 1		NCR#:	Is N	Is NCR ? : No	
Defect Details							
During test SW pump # 2 we found that , high vibration on entaired pump and smock coming from shaft seal when pump running. No pressure rise on SW line							
Requisition Code:							
Categories							
Primary:	E/R Machinery	Inspector - Internal :			Vessel Dept:	Engine	
Secondary:	Miscellaneous	Inspect	or External :		Office Dept:	Technical	
		Inspect	ion Date :				
Applicable Dates							
Date Raised: 27-May-2023			ETC: 03-Jun-2023		Date Completed :		
Other Details							
Priority : Normal			Assigned By: Vessel		Verified By :		
Display in Daily Meeting? : No			SFI:		Verified On:		
Causes							
Corrective Action							
Preventive Action							
Applicable Tags							
Root Causes- Job Factor							
Inadequate Maintenance							
Follow Up							
On	Ву		Follow Up				
Before & After Pictures							
Before				After			

Defect List Details Printed On: 21-Jun-2023 1/1