



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | | |
|------------------------|---------------|---------|---------------|
| Vessel : Kensington LG | Defect ID : 1 | NCR # : | Is NCR ? : No |
|------------------------|---------------|---------|---------------|

Defect Details

During test SW pump # 2 we found that , high vibration on entaired pump and smock coming from shaft seal when pump running.
No pressure rise on SW line

Requisition Code :

Categories

| | | | | | |
|-------------|---------------|------------------------|--|---------------|-----------|
| Primary : | E/R Machinery | Inspector - Internal : | | Vessel Dept : | Engine |
| Secondary : | Miscellaneous | Inspector External : | | Office Dept : | Technical |
| | | Inspection Date : | | | |

Applicable Dates

| | | |
|---------------------------|-------------------|------------------------------|
| Date Raised : 27-May-2023 | ETC : 03-Jun-2023 | Date Completed : 05-Jun-2023 |
|---------------------------|-------------------|------------------------------|

Other Details

| | | |
|--------------------------------|----------------------|---------------|
| Priority : Normal | Assigned By : Vessel | Verified By : |
| Display in Daily Meeting? : No | SFI : | Verified On : |

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Follow Up

| On | By | Follow Up | |
|----|----|-----------|--|
|----|----|-----------|--|

Before & After Pictures

| Before | After |
|--------|-------|
|--------|-------|