



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 155	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Sealing rubber gasket for various vents/flaps in forecastle deck (like Bosun store flaps etc..) are deteriorated upto extent where it fails to provide adequate sealing arrangements to the respective compartments. This must be investigated and to be renewed on priority.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 15-Nov-2021	Date Completed : 25-Oct-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Follow Up

On	By	Follow Up	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before

After

