



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 159	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Ergonomical hazard while accessing valve - T.O.B. Room main valve is situated at a height of almost 8 feet from the floor and one stand with height of 2-3 feet could be sighted for accessing this valve operation however with present arrangement also system not looks effective hence suggest to increase the height of platform suitable for the operator so that valve could be operated without putting any strain on his upper body.

Requisition Code :

Categories

Primary :	Fittings	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Engine
Secondary :	Fixture	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 30-Nov-2021	Date Completed : 10-Jan-2022
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
12/Jan/2022	Danut Pompiliu Neagu Staff Code - 10428 - C/E	Job done	Link1
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before	After
--------	-------

