

Maritec Tanker Management Defect List Details

Ship File No: N/A
Office File No: N/A
Form No: N/A
Issue: N/A
Revision: N/A
Rev Date: N/A

Vessel: Bitu Atlantic Defect ID: 166 NCR #: Is NCR ?: No

Defect Details

Fire control station, Passage to Hypermist release cabinet for E/R are not cleared as SCBA box was found lying in front of cabinet making the area inaccessible. Ship staff must ensure that passage to any FFA equipment/cabinets must be kept clear at all times.

Requisition Code:

Categories								
Primary :	LSA/FFA	Inspector - Internal :	Nawin Khaware	Vessel Dept:	Deck			
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept:	Safety			
		Inspection Date :	27-Sep-2021					

Applicable Dates

Other Details						
Priority : Urgent	Assigned By: HSQE Suptd	Verified By :				
Display in Daily Meeting? : No	SFI:	Verified On:				

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Personal Factor

Others

Follow Up

On	Ву	Follow Up	
03/Nov/2021	Naeem Kalangadan Staff Code - 10375 - 3/OFF	scba box position changed now area is clear and well accessible to pass to Hypermist panel. All passages are cleared	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Defect List Details Printed On: 04-Apr-2022 1/2

Before After



