



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 157	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Light covers of following places are found broken - Pump room 2nd and 4th platform, E/R bottom platform - near emergency exit.

Requisition Code : ATLC-SOT-V210306

Categories

Primary :	Fittings	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Engine
Secondary :	Fixture	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 25-Oct-2021	Date Completed : 29-Nov-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up

On	By	Follow Up	
09/Oct/2021	ANUJ KUMAR Staff Code - 10276 - E/O	Replaced broken cover in E/R. Pump room light covers not held in stock. Requisition ATLC-SOT-V210306	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before	After
--------	-------

