



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 154	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Brake liner of mooring winch forward mooring winch outer drum has been thinned down and requiring replacement. During mooring operation at Tarragona, found mooring brake was holding satisfactorily however it is prudent to get this changed on priority as vessel doing several STS operations at Lome where strain on ropes are likely to be high and the present condition might pose a risk to mooring safety.

Requisition Code :

Categories

Primary :	Dk Machinery	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Mooring Winch	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 15-Nov-2021	Date Completed : 04-Oct-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up

On	By	Follow Up	
28/Oct/2021	Nawin Khaware	After renewing the brake liner, carry out brake holding test of that winch and upload the test report.	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before



After

