



Maritec Tanker Management

Defect List Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 170	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Both side Gangway Lifebuoy S.I. Lights were not working properly, same was rectified by the attending officer once pointed out to him. However vessel should ensure a routine maintenance on LSA/FFA items are performed diligently and same must be verified by Senior officer during rounds.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 30-Oct-2021	Date Completed : 27-Sep-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Personal Factor

Others

Follow Up

On	By	Follow Up	
30/Oct/2021	Naeem Kalangadan Staff Code - 10375 - 3/OFF	checking every week properly all LSA AND FFA and record keeping properly . It will not repaat again	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before



After

