



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Express	Defect ID : 307	NCR # :	Is NCR ? : No
-----------------------	-----------------	---------	---------------

Defect Details

Transfer Pump #2 FO for Main Engine and Generatators Coupling Shaft without cover protections.
Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :			

Applicable Dates

Date Raised : 29-Jan-2023	ETC : 28-Feb-2023	Date Completed : 01-Feb-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
----	----	-----------	--

29/Jan/2023	Marin Panait Staff Code - 10017 - MST	Ship Design without Cover Protection. Vessel will fabricate on board this cover protections.	Link1 Link2 Link3 Link4 Link5 Link6 Link7 Link8 Link9 Link10 Link11
-------------	--	---	---

Before & After Pictures

Before	After
--------	-------









