

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic Defect ID : 150 NCR # : Is NCR ? : No	
---	--

Defect Details

Soot collection tank is in poor condition- maintenance required

Requisition Code:

Categories							
Primary :	Others	Inspector - Internal:	Vikram Puri	Vessel Dept:	Engine		
Secondary :	Others	Inspector External :		Office Dept:	RAME		
		Inspection Date :	31-Jul-2021				

Applicable Dates

Date Raised: 31-Jul-2021 ETC: 08-Sep-2021 Date Completed: 09-Sep-2021

Other Details

Priority: Normal Assigned By: Tech Suptd Verified By:

Display in Daily Meeting?: No SFI: Verified On:

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up

On	Ву	Follow Up	
26/Sep/2021	Stelian BOGHEA - Staff Code - 10166 - C/E	Will be necessary to replace the bottom frame plate due to corrode.	
31/Aug/2021	Kamlesh Jalori		

Before & After Pictures

Defect List Details Printed On: 04-Apr-2022 1/2









Defect List Details Printed On: 04-Apr-2022 2/2