

Unsafe Act or Condition

| Vessel : Asphalt Teranga | | | | |
|---|----------------------------|---|------------------|---|
| Report Date: 13-Apr-2023 | | | | |
| Location : engine room bottom platform | | | | |
| Unsafe Act Or Condition: | | | | |
| Type : Unsafe Act | | | | |
| Brief Details : While opening the themal boiler motor a crew member was using open end spaner size 19, crew member was stopped and asked to use ring side of the spanner. | | | | |
| Was action taken at the time? | ': Yes | | | |
| Was work stopped? : | Yes | | | |
| Officer notified? : | Yes | 2/E was n | otified and same | was discussed in next tool box meeting. |
| Action successful? : | Yes | | | |
| Report anonymous? : | Yes | 2/E was notified and same was discussed in next tool box meeting. | | |
| Any other comments or suggestions? Enter below: | | | | |
| Brief Details : Concur with action plan, On sight training plays an integral role in improving work culture onboard the ship. | | | | |
| Date Reviewed by DPA : 20-Apr-2023 | | | | |
| Actions : | | | | |
| Tick further Actions : N | No Further action required | | Remarks : | |
| Link NC/Observation/Near Miss/ Risk Assessment : | | | | |
| Followup Completed : Yes | | | | |