

Unsafe Act or Condition

Vessel : Asphalt Teranga				
Report Date: 13-Apr-2023				
Location : engine room bottom platform				
Unsafe Act Or Condition:				
Type : Unsafe Act				
Brief Details : While opening the themal boiler motor a crew member was using open end spaner size 19, crew member was stopped and asked to use ring side of the spanner.				
Was action taken at the time	e? : Yes			
Was work stopped? :	Yes			
Officer notified? :	Yes	2/E was notified and same was discussed in next tool box meeting.		
Action successful? :	Yes			
Report anonymous? :	Yes	2/E was notified and same was discussed in next tool box meeting.		
Any other comments or suggestions? Enter below:				
Brief Details : Concur with action plan, On sight training plays an integral role in improving work culture onboard the ship.				
Date Reviewed by DPA : 20-Apr-2023				
Actions :				
Tick further Actions :	No Further action required		Remarks :	
Link NC/Observation/Near Miss/ Risk Assessment :				
Followup Completed : Yes				