



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bahama Blue		
Report Date : 08-Feb-2023		
Location : Deck Starboard side manifold		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : Vessel at berth in St. Croix for loading. Duty officer found out that manifold starboard side diptry drain plug was not tight.		
Was action taken at the time? :	Yes	Check the darin plug and tight the plug
Was work stopped? :	Yes	Check the darin plug and tight the plug
Officer notified? :	No	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : This items must be checked during regular rounds on deck, we concur with action plan of the vessel.		
Date Reviewed by DPA : 15-Feb-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		