



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | |
|--|----------------------------|---|
| Vessel : Bahama Blue | | |
| Report Date : 08-Feb-2023 | | |
| Location : Deck Starboard side manifold | | |
| Unsafe Act Or Condition: | | |
| Type : Unsafe Condition | | |
| Brief Details : Vessel at berth in St. Croix for loading. Duty officer found out that manifold starboard side diptry drain plug was not tight. | | |
| Was action taken at the time? : | Yes | Check the darin plug and tight the plug |
| Was work stopped? : | Yes | Check the darin plug and tight the plug |
| Officer notified? : | No | |
| Action successful? : | Yes | |
| Report anonymous? : | No | |
| Any other comments or suggestions? Enter below: | | |
| Brief Details : This items must be checked during regular rounds on deck, we concur with action plan of the vessel. | | |
| Date Reviewed by DPA : 15-Feb-2023 | | |
| Actions : | | |
| Tick further Actions : | No Further action required | Remarks : |
| Link NC/Observation/Near Miss/ Risk Assessment : | | |
| Followup Completed : Yes | | |