



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue		
Report Date : 23-Apr-2023		
Location : Engine Room		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : While carrying out weekly LSA and FFA inspection, it was observed that the EEBD in the engine room was defected. The bottle pressure was showing a reading of 0(redzone).		
Was action taken at the time? :	Yes	Master was informed. EEBD was replaced with a spare EEBD.
Was work stopped? :	No	Master was informed. EEBD was replaced with a spare EEBD.
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Agreed with action plan, ensure all LSA/FFA items are maintained in good working condition at all times.		
Date Reviewed by DPA : 26-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		