

## **Unsafe Act or Condition**

| Vessel : Biskra   |                                      |  |
|---|--------------------------------------|--|
| Report Date: 15-Apr-2023  |                                      |  |
| Location : Main Deck  |                                      |  |
| Unsafe Act Or Condition:  |                                      |  |
| Type : Unsafe Condition   |                                      |  |
| Brief Details : While approching Durban port a crew member noticed ,hydrualic line leaking on main deck, same immediately rectified and repaired. |                                      |  |
| Was action taken at the time?   | : Yes                                |  |
| Was work stopped? :   | No                                   |  |
| Officer notified? :   | Yes                                  |  |
| Action successful? :  | Yes                                  |  |
| Report anonymous? :   | No                                   |  |
| Any other comments or suggestions? Enter below:   |                                      |  |
| Brief Details : Concur with action plan.  |                                      |  |
| Date Reviewed by DPA : 21-Apr-2023  |                                      |  |
| Actions :   |                                      |  |
| Tick further Actions : No   | No Further action required Remarks : |  |
| Link NC/Observation/Near Miss/ Risk Assessment :  |                                      |  |
| Followup Completed : Yes  |                                      |  |