

## **Unsafe Act or Condition**

Vessel : Biskra		
Report Date: 15-Apr-2023		
Location : Main Deck		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : While approching Durban port a crew member noticed ,hydrualic line leaking on main deck, same immediately rectified and repaired.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan.		
Date Reviewed by DPA : 21-Apr-2023		
Actions :		
Tick further Actions : No	Further action require	ed Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		