



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 03-Apr-2023		
Location : DECK		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : Midship crane operating lever hyd. oil leakage. The oil dripped to the platform which make slippery on climbing the crane steps.		
Was action taken at the time? :	Yes	Clean the steps with rags before and after operation of crane.
Was work stopped? :	No	Clean the steps with rags before and after operation of crane.
Officer notified? :	Yes	Reported to officer and engineers.
Action successful? :	No	
Report anonymous? :	No	Reported to officer and engineers.
Any other comments or suggestions? Enter below:		
Brief Details : Keep all the working pace area free from any oil stains to avoid slip/trip/fall hazards.		
Date Reviewed by DPA : 10-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		