



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 10-Apr-2023		
Location : DECK		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During cargo discharging operation with MT. Bitu River . Vessel yellow No.2 Manifold Valve found leakage.		
Was action taken at the time? :	Yes	Report to oow to stop the cargo discharging. Pumpman and bosun tighten up the bolts.
Was work stopped? :	Yes	Report to oow to stop the cargo discharging. Pumpman and bosun tighten up the bolts.
Officer notified? :	Yes	Reported to CCR
Action successful? :	Yes	Resume discharging through Yellow manifold.
Report anonymous? :	No	Reported to CCR
Any other comments or suggestions? Enter below:		
Brief Details : Good observation and concur with action plan. same level of alertness is required by deck watch keepers during cargo operation.		
Date Reviewed by DPA : 17-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		